

JAMUNA RIVER EROSIONAL HAZARDS, ACCRETION & ANNUAL WATER DISCHARGE—A REMOTE SENSING & GIS APPROACH

E.U.Pahlowan^{a,*}, A.T.M. S. Hossain^b

^a Department of Geological Sciences, Jahangirnagar University, Savar, Dhaka-1342, Bangladesh – ershadudp@yahoo.com

^b Professor, Department of Geological Sciences, Jahangirnagar University,
Savar, Dhaka-1342, Bangladesh – shakhawathos2004@yahoo.com

KEY WORDS: Jamuna River, Hazard, Remote Sensing, NDWI, Erosion, Accretion

ABSTRACT:

This paper presents the results of some of the Jamuna River erosional hazards from Bahadurabad Ghat to Bhuapur (near Jamuna Bridge). Results are also presented on the Jamuna River accretion and water discharge. Landsat images from 1977 to 2014 and water discharge data were analysed to find out a relationship between dynamics of erosion and accretion for different time intervals with average annual water discharge. It is clearly established that total amount of erosion and accretion rates varies with different times. The highest erosion rate $21.15 \text{ km}^2 \text{ year}^{-1}$ was observed in the period of 1989-1992 and the highest accretion rate $13.57 \text{ km}^2 \text{ year}^{-1}$ was observed in the period of 1980-1989. The erosion and accretion values fluctuated with increasing average annual maximum water discharge but the difference between erosion and accretion had remained low before water discharge reached to $67000 \text{ m}^3 \text{ s}^{-1}$ and it is estimated higher after crossing annual average maximum water discharge of $67000 \text{ m}^3 \text{ s}^{-1}$. This discharge value also plays an important role on bar development and active channel. It is also observed that unvegetated bar areas remained higher than active channel areas before average annual maximum water discharge reached to $67000 \text{ m}^3 \text{ s}^{-1}$. Finally, all the erosional hazards and accretion values are compared and evaluated to see their influence on the annual discharge.

1. INTRODUCTION

Bangladesh is familiar globally with the countries most disclosed to the influence of global warming and climate change. This is owing to its exceptional geographical location, supremacy of floodplains and low altitude from the sea and seductive dependence on nature. Riverbank erosion is a familiar natural disaster of Bangladesh and an issue of major distress. It causes indescribable desolations yearly people living alongside the banks of rivers in Bangladesh and turns into hazards. River bank erosion treats as geomorphic hazards. Geomorphic hazards demarcated as the instability of earth surface features treat that's threat for human civilization (Gares et al., 1994). These features are significantly intense on landform response. Since 1973 major rivers similar to the Jamuna, the Ganges and the Padma have eroded around $1,590 \text{ km}^2$ of floodplains making 1.6 million people homeless. Not only the floodplain inhabitants, but also the char land inhabitants are defenceless to river erosion (Aktar, 2013).

The Jamuna is the name known to the braided river downstream of the Old Brahmaputra distributary and is one of three large sand-bed rivers that cross the low-lying deltaic floodplain of Bangladesh (Ashworth, 1996). The Jamuna River grows in the Tibetan plateau, and 93% of its catchment lays outward of Bangladesh. By 2740 km beginning from its source and 220 km from the north borders of Bangladesh, the Jamuna contacts with the Ganges (after that becoming the 'Padma') and then the Meghna, finally discharging into the Bay of Bengal (Ashworth, 1996). Jamuna have a history of 250 years (Bhuiyan et al., 2010). Since then the Jamuna River has sustained stable course, often detached by small islands/sandbars, called chars, within

the course. Unstable banks and rapid rates of sideways movement characterize this river. To arrange channels and chars within the Jamuna River changes by the year in response to the time's sequence of flows (Khan and Islam, 2003). The annual discharge values are around $60000 \text{ m}^3 \text{ s}^{-1}$ which is three times greater than the Mississippi (Coleman, 1969) and may exceed $100000 \text{ m}^3 \text{ s}^{-1}$ in a 100-year flood (Halcrow et al., 1992). Amalgamation of variable discharges of water and sediment is responsible for the Jamuna's braided plan. Braided rivers are regarded as unstable bank lines and rapid rates of sideways movement. There is sign of severe bank erosion and rapid rates of bank line retreat along the Jamuna River (Khan and Islam, 2003). The fourth Intergovernmental Panel on Climate Change (IPCC) Report forecasts for South Asia that monsoon rainfall will be higher, resulting in increased flows during the monsoon in the rivers. These flow will change the flood regimes and increase bank erosion (Rahman et al., 2010). Current climate change will alter the precipitation pattern including change in runoff and subsurface flow that have direct impact on future water ability of Jamuna River. Already The Jamuna has experienced expansion of flow over the years. Heavy rain on its catchment area and water level rising by extreme snowmelt will increase discharge in future years due to current global warming (Rajib et al., 2011).

This study targets to discover a relation between discharge and erosion of Jamuna River as well as the influence of climate changes on river morphology. Since there is no record on riverbank erosion, active channel area, unvegetated bars, and vegetated island, this study is focused to measure it using satellite images. Yet, the present study has combined with RS, GIS and water discharge. Landsat images from 1977-2014 are

* Corresponding author. Tel.: +880-01819693854. E-mail address: ershadudp@yahoo.com (E.U.Pahlowan).

analysed for assessing active channel area, vegetated island, unvegetated bars, erosion and accretion of land along both sides of the river.

2. STUDY AREA

The Jamuna, geologically youngest River of the world (Archana and Nayan, 2012). Because of abnormal flood and tectonic movement Brahmaputra river started its flow through a new course known as Jamuna from 1787 (Uddin et al., 2011). The starting point of the study area is Bahadurabad and the end point is Bhuiyapur. The investigated area is located (Figure 1) in between Latitude 24°20'-25°10'N and Longitude 89°30'-89°50'E. From the technical point of view, these two points have important significance in terms river flow and erosion (Ashworth, 1996). Because Bahadurabad is immediately upstream part experiencing river bank retreated and Bhuiyapur area river training works corrode Jamuna (Bhuiyan et al., 2010)..




Figure 1. Location of Study Area

3. GEOMORPHOLOGY AND HYDROGEOLOGY

The Jamuna displays dangerous forceful nature through its bank erosion rate (Coleman, 1969) and (Klaassen and Masselink, 1992). Gradual tilting triggered deviate of the Jamuna from the Brahmaputra and floodplain is aggressively descending due to echelon fault. The Jamuna contains different types and size of bars, Megaforms and Macroforms of bar in the Jamuna from hierarchical bedform classification (Jackson, 1975). Mid channel bar, one of the most common bar types in the Jamuna River. The actions and morphology of mid-channel bars in the Jamuna is strongly time dependent. Although bars also emergent without a change in flow stage or discharge because of anabranch cut (Leopold et al., 1957) and (Ashmore, 1982). The annual monsoons and tectonic settings dominate the sediment discharge in Jamuna (Rajib et al., 2011) and (Ashworth, 1996).

4. MATERIAL AND METHOD

4.1. Data

The basic data of the study area are Landsat satellite images of different years from 1977 to 2014. United States of Geological Survey (USGS) provides TM, MSS, ETM+, AND OLI (Path 148 and Row 43) images in the earth explorer website: <http://earthexplorer.usgs.gov>. All satellite images have taken at dry seasons. Atmospheric corrections were done for accuracy of the information that was extracted from different Landsat images. Geometric corrections were performed to fix each image into the UTM-46N projection. Because of flat land, the orthogonal transformation was not performed. All images were resample with the nearest neighbor method to a common resolution of 30m. Erdas Imagine software has been used for processing satellite images and analysis of the riverbank data. For analyzing, the historical flow patterns of Jamuna River from average yearly discharge data are collected from Bangladesh Water Development Board (BWDB). BWDB has historic records of Jamuna River discharge data frequency from many years from 1977-2006 were separately analyzed by using M.S. Excel to see the difference of flow

Satellite	Sensor	Path/Row	Pixel size(m)	Date/year
Landsat 8	OLI	148/043	30	2014
Landsat 7	ETM+	148/043	30	2011
Landsat 7	ETM+	143/043	30	2004
Landsat 7	ETM+	143/043	30	2000
Landsat 5	TM	143/043	30	1992
Landsat 5	TM	143/043	30	1989
Landsat 4	TM	143/043	30	1980
Landsat 3	MSS	143/043	60	1977

Table 1. Landsat images are used for extracting the information

4.2. Methodology

Satellite images for years 1977 and 2014 are used to get the important information about the study area. A detail methodology for extraction of the information from LS images is shown in Figure 2.




Figure 2. Methodology

4.3. Preparation of NDWI and NDVI Image

The principle of NDWI (Normalized difference water index) (McFeeters) is similar to Normalized Difference Vegetation Index (NDVI). NDVI strengthen the presence of terrestrial vegetation and open water feature suppress from the soil features because of the different ways in which these features reflect these wavelengths McFeeters (McFeeters, 1996). NDVI values that are higher than zero consider as vegetated area and are less than zero consider as unvegetated area. The formula of NDVI as follows: $(NIR - Red) / (NIR + Red)$. By reversing the equation and the green band used rather than the red, and then the result will reversed. The vegetation suppressed and the open water features strengthened (McFeeters, 1996). Though Landsat Multispectral Scanner (MSS) image data first used for NDWI (McFeeters), it is applicable for other sensor to find out extending open water. The equation for an NDWI is: $(Green - NIR) / (Green + NIR)$. (McFeeters, 1996) highlighted on the values of NDWI, which is larger than zero as water surfaces, which values are less than characterize to be non-water surfaces. For minimizing, the errors of selected feature to mottled pixels that are closest to water body and other low reflectance objects, only selected those pixels that has highest NDWI value. The sorted pixels than converted into one of the proposed class (signature) through use of mathematically settled on decision rule (maximum likelihood). Finally, identified the land cover features to which each proposed class matched. Active channel, Vegetated bar, and Unvegetated bar are identified from the image of NDWI and NDVI.

4.4. Demarcation of Jamuna River Bank Line

The river bank-line has been recognized and delimited aimed at all satellite images of 1977-2014. NDWI image is very useful for recognizing the river bank-line. Where the shallow water channel is considering as a part of river, old or newly deposited sand and silt near the riverbanks posture various doubt of interpretation as the river. The darker tone on satellite image, showing higher moisture and several soil spots those is close on the active water channel give sign and show bright signature and of low moisture. Here NDWI demark the area between higher and lower moisture content as well as bank line. Nevertheless, river flowing over recently when there was high flow and consider as a part of river. The identified river bank-line of the river, have been digitized in Arc Gis -10.1 software. Two riverbank lines have been prepared for the year 1977, 1980, 1989, 1992, 2000 2004, 2011, and 2014. Both left and right banks for all years have been identified using GIS software. Riverbank erosion and deposition has been calculated by superimposing two successive bank lines.

5. RESULTS AND DISCUSSIONS

From the analysis, a series of different Landsat images from 1977 to 2014 reveal the yearly rates of erosion and accretion and their differences with different time in Figure 3 & Table 2. Through the time erosion and accretion are varied at different periods. The highest erosion rate was $21.15 \text{ km}^2\text{year}^{-1}$ in the period of 1989-1992 and the lowest erosion rate was $8.61 \text{ km}^2\text{year}^{-1}$ in the period of 2011-2014. However, erosion rates swing between $17 \text{ km}^2\text{year}^{-1}$ to $10 \text{ km}^2\text{year}^{-1}$ in the other periods. The summation of erosion rate from 7 different periods is $14.58 \text{ km}^2\text{year}^{-1}$ and total land loss due to bank erosion was 540 km^2 . The highest accretion rate was $13.57 \text{ km}^2\text{year}^{-1}$ in the 1980-1989 periods and lowest was $3.65 \text{ km}^2\text{year}^{-1}$ in 2004-2011 period but rate remains in between (4 to 9) $\text{km}^2\text{year}^{-1}$ in other

periods. Again, summation of 7 individual periods, total land gained by accretion was 185 km^2 . The total land loss from 7 individual periods due to erosion was 160 km^2 and net land loss because of erosion was 107 km^2 . So the remaining 53 km^2 land was reworked during the period of 1977-2014. From this analysis, it is established that accretion and erosion were vigorous during this period. The total land change was about -107 km^2 , pointing out the overall loss of land was the dominant for the same period.




Figure 3. Erosion and Accretion rate

Period	Accretion ($\text{km}^2\text{year}^{-1}$)	Total accretion (km^2)	Erosion ($\text{km}^2\text{year}^{-1}$)	Total erosion (km^2)	Difference (km^2)
1977-1980	7.64	22.94	16.64	49.92	-26.98
1980-1989	13.57	122.13	14.11	127	-4.87
1989-1992	5.91	17.73	21.15	63.47	-45.73
1992-2000	13.24	105.96	17.54	140.38	-34.42
2000-2004	9.74	38.98	10.48	41.95	-2.97
2004-2011	3.65	25.6	11.25	78.78	-53.18
2011-2014	6.04	18.13	8.61	25.85	-7.72
Total	9.49	351.47	14.25	527.35	-175.87
1977-2014	4.29	158.96	7.18	266	-107.04

Table 2. Accretion and erosion rates of Jamuna riverbank estimated for entire period of study




Figure 4. Bars area with time

The total area of river have been divided into three areas they area active channel area, Unvegetated Bar area and Vegetated Bar area. From Figure 4 maximum active channel area was 442 km² in 2005. Minimum active channel area was 228 km² in 1977. The maximum vegetated and unvegetated bar area was 291.71 km² and 552.58 km² during 2014 and 1992 respectively. In addition, minimum vegetated & unvegetated bar area was 148 km² and 318 km² during 1992 and 1989 respectively. Vegetated bars remain stable for several years and flooded during full stage of bank. Whereas unvegetated bars are composed by newly deposited sediment and reworked during every monsoon. The area of unvegetated bars remains higher than vegetated bars in every measurement. It indicates the dynamic nature of Jamuna on its bar depositions and erosions. These erosions and depositions have greater influence on riverbank erosion and accretion.




Figure 5. Bar dynamics with discharge

It can be seen from figure 5 that shows that water discharge control the river dynamics. Unvegetated bars area and active channel areas are fluctuated with increasing water discharge. But it significantly change when average annual maximum water discharge reached 67000 m³s⁻¹. Unvegetated bar area remains higher than active channel area before average annual maximum water discharge reach 67000 m³s⁻¹. After crossing average annual maximum water, discharge 67000 m³s⁻¹ channel area tends to be greater than the area of unvegetated bars. The excess water, which is more than 6700 m³s⁻¹, firstly erodes the unvegetated bars after those vegetated bars. These bar erosions help to change the river morphology during monsoon.




Figure 6. Erosion and Accretion with discharge

A relationship between river erosion accretion with discharge is shown in figure 6. It is observed that the erosion always greater than the accretion. Erosion show large fluctuation of area in a range of 42 km² to 140 km² over the past 37 years with general increasing trend. On the other hand, accretion ($r = .126$) shows less variation than erosion ($r = .321$) with general increasing pattern's. The erosion and accretion showing with increasing average annual water discharge but the difference between erosion and accretion remains low before water discharge reaches 67000 m³s⁻¹. Erosion and accretion tend to be higher after crossing annual average maximum water discharge 67000 m³s⁻¹. The calculated 35 year average maximum water discharge of the Jamuna River at Bahadurabad is 67435 m³s⁻¹ from 1971-2006 which is more than 67000 m³s⁻¹. In the future year Jamuna will continue to increase its discharge due to ongoing climate change, which will increase its average annual discharge. Therefore, average annual maximum water discharge 67000 m³s⁻¹ is a minimal discharge value for controlling the erosion and the accretion of Jamuna River. Erosion can be reduced by withdrawing excess water discharge from Jamuna.

6. CONCLUSION

The present study is focused on a relation between river dynamics and water discharges. Cloud free different Landsat images were used for riverbank delineation and water discharge data were used for statistical analysis. Landsat data has revealed the changes of river morphology due to annual water discharge. Due to on-going climate change, Jamuna River change its natural trend by change its bank line and bars area. In the study area, Jamuna exhibit different rate of erosion and accretion during 37 years. The net land change was about -107 km², indicating the overall loss of land was the dominant process for the period of study. From 1971-2006 average annual discharge of the Jamuna River at Bahadurabad is 67435 m³s⁻¹. Nevertheless, annual average discharge 67000 m³s⁻¹ is a crucial value for drastically change the accretion and erosion rate. (Gares et al., 1994) Discharge continuously changes the size of different bars and the area of active channel during study period. These bars trigger the bank erosion and the accretion rate of Jamuna River. By using this information compiled with other data like short-term intense rainfall in the catchment area of Jamuna river will serve to taking up a long-term prediction for erosion and accretion.

REFERENCE:

Aktar, M.N., 2013. Impact of Climate Change on Riverbank Erosion. *International Journal of Sciences: Basic and Applied Research (IJSBAR)* 7, 36-42

Archana, S., Nayan, S., 2012. RS-GIS based assessment of river dynamics of Brahmaputra river in India. *Journal of Water Resource and Protection* 2012.

Ashmore, P.E., 1982. Laboratory modelling of gravel braided stream morphology. *Earth Surface Processes and Landforms* 7, 201-225.

Ashworth, P.J., 1996. Mid-channel bar growth and its relationship to local flow strength and direction. *Earth Surface Processes and Landforms* 21, 123.

Bhuiyan, M.A., MA, R., Kumamoto, T., M Julleh Jalalur, R., Shigeyuki, S., 2010. Regulation of Brahmaputra-Jamuna River around Jamuna Bridge Site, Bangladesh: Geoenvironmental Impacts. *Journal of Water Resource and Protection* 2010.

Coleman, J.M., 1969. Brahmaputra River: channel processes and sedimentation. *Sedimentary Geology* 3, 129-239.

Gares, P.A., Sherman, D.J., Nordstrom, K.F., 1994. Geomorphology and natural hazards. *Geomorphology* 10, 1-18.

Halcrow, S.W., Partners, institut, D.h., Borđa, B.P.U., 1992. River Training Studies of the Brahmaputra River, River Bank Protection Project, Brahmaputra Right Bank Priority Works: Environmental Impact Assessment. Sir William Halcrow & Partners Limited.

Jackson, R.G., 1975. Hierarchical attributes and a unifying model of bed forms composed of cohesionless material and produced by shearing flow. *Geological Society of America Bulletin* 86, 1523-1533.

Khan, N.I., Islam, A., 2003. Quantification of erosion patterns in the Brahmaputra–Jamuna River using geographical information system and remote sensing techniques. *Hydrological Processes* 17, 959-966.

Klaassen, G.J., Masselink, G., 1992. Planform changes of a braided river with fine sand as bed and bank material.

Leopold, L.B., Wolman, M.G., Wolman, M.G., Wolman, M.G., 1957. River channel patterns: braided, meandering, and straight. McFeeters, S., 1996. The use of the Normalized Difference Water Index (NDWI) in the delineation of open water features. *International journal of remote sensing* 17, 1425-1432.

Rahman, M.U., Sarwat Jahan, Kamal, M.M., 2010. Response of Climate Change on the morphological behavior of the major river system. *Institute of Water Modelling*

Rajib, M.A., Rahman, M.M., McBean, E.A., 2011. Application of regional climate model simulation and flow data for assessing future water availability in the River Jamuna. *Int. J. Environ. Sci* 1, 884-896.

Uddin, K., Shrestha, B., Alam, M.S., 2011. Assessment of Morphological Changes and Vulnerability of River Bank Erosion alongside the River Jamuna Using Remote Sensing. *Journal of Earth Science and Engineering* 1, 30-35.

APPENDIX



Figure 7. Unvegetated bar erosion at Char Maina Jamuna River, Jamalpur.



Figure 8. Govt. Primary School at Belgacha facing serious threat of bank erosion .



Figure 9. Vegetated bar erosion at Char Barul, Jamuna River, Jamalpur.



Figure 10. Bank erosion 6 km south from Bahadurabad.